



interior



rear view



after



before



before



after

Squirrel Hill, Pittsburgh PA • 1999

Addition of great room, masterbath, kitchen, 2nd floor bedroom and bath to a 70 yr. old residence. Bland and closed interior was opened to backyard with dormer and glass doors leading to a dressy wood deck with graciously descending stair.